

# APK Installation guide for D22 rev1

## Purpose:


The APK "GLP FuncTest.apk" is to calibrate Accelerometer, Ambient Light Sensor and Proximity Sensor

This calibration is needed if main PBA or Front cover is replaced.


**There are 4 chapters in this guide.**

- 1. USB driver installation.**
- 2. How to install D22 calibration APK.**
- 3. How to calibrate**
- 4. How to remove the APK and disable USB debugging.**


✧ Before installation, please go to device and press menu key → "Settings" → "About phone" hit "Build number" 7 times.



“Developer options” menu item will be showed in “Settings” page.




Enable "USB" debugging




## 1. USB driver installation:

- Since the APK need to be installed by ADB command, please install USB driver first.

Open USB driver install\_D22 from package.




Double click [Install ADB drivers.bat](#) to install ADB driver.




## 2. How to install D22 calibration APK\_xx

Prepare a PC and connect to device with USB cable and **wait** for USB driver installs.


Open D22 Calibration APK folder.



Double click [Install\\_D22\\_calibration.bat](#) to install calibration Apk.



Important: Allow USB debugging on phone



Below screenshot should be shown in PC:

```
C:\Windows\system32\cmd.exe

C:\Users\23049357\Desktop\Sony D22\D22 Calibration APK>"C:\Users\23049357\Desktop\Sony D22\D22 Calibration APK"\adb\adb wait-for-devices

C:\Users\23049357\Desktop\Sony D22\D22 Calibration APK>"C:\Users\23049357\Desktop\Sony D22\D22 Calibration APK"\adb\adb install "D22 Calibration.apk"
4772 KB/s (1759442 bytes in 0.359s)
pkg: /data/local/tmp/D22 Calibration.apk
Success


C:\Users\23049357\Desktop\Sony D22\D22 Calibration APK>pause
Press any key to continue . . .
```

If **Success**, the APK are installed.


**Unplug USB cable**

The USB connection will interfere with calibration.

Select “GLP FuncTest” icon to enter calibration menu.




There would be 3 items presented for the calibration process.




### 3. How to calibrate.

Follow instructions in APK Calibration user manual.



#### 4. How to remove the APK and disable USB debugging.

Press Uninstall.



Then uninstall page will be shown up. Press "Uninstall".

Please go to device and press menu key → “Settings” → “Developer options” to disable “USB debugging”

