




Part List, SP/Mech

Applicable for T226

Contents

1	Exploded View.....	2
2	Common Parts.....	3
3	Variant Parts	3
4	Revision History	4

1 Exploded View





2 Common Parts

Pos	Description	Part Number	Comments
1	Battery Door, light blue	SXA 134 1688/2	
2	Label	SVF 930 2239	Requires LabelMake capability
3	Screw, 4.5mm (black)	SXA 109 3391/54	Quantity two
4	Screw, 7.4mm (gold)	SXA 109 3391/74	Quantity four
5	Frame, dark blue	SXA 134 1694/2	Requires LabelMake capability
6	Speaker Grommet	SXA 134 1712	
7	Polyphonic Speaker, 15 mm	RLE 907 16	
8	Speaker Pad	SXA 134 900	
10	Keypad PCB Assembly Complete	SXK 109 5304/Z	
12	Microphone Grommet	SXA 134 0216	
13	Microphone	RLC 509 409/43	
14	Front Assembly, light blue cover, dark blue window	SXK 107 1548/8	
15	Cobrand Tape	SXA 134 1750	
17	SEMC Icon, Plastic 8mm	SXA 109 3019	Changed from SVF 930 392
18	Antenna Cover, light blue	SXA 134 1696/2	
19	Antenna Assembly	SXK 109 5826	
20	Side Volume Button, dark blue	SXA 134 1695/2	
21	Side Volume Switch	RMD 955 116/1	
22	LCD	RNH 942 211	
23	Vibrator Complete	BKE 903 24	
24	Receiver (Loudspeaker)	RLE 907 21	
25	Receiver Gasket	SXA 134 1689	
26	Speaker Cloth	SXA 134 1693	
27	Dust Gasket	SXA 134 1715	Use R2A

3 Variant Parts

Pos	Description	Part Number	Comments
11	Keypad Complete, light blue keys/ dark blue navigation button	SXK 109 5297/21	Generic
	Keypad Complete, light blue keys/ dark blue navigation button	SXK 109 5297/254	AT&T
	Keypad Complete, light blue keys/ dark blue navigation button	SXK 109 5297/230	Cingular
16	Cobrand Inlay, light blue	SXA 134 1732/402	AT&T
	Cobrand Inlay, light blue	SXA 134 1732/412	Cingular
	Cobrand Inlay, light blue	SXA 134 1732/2	Generic



4 Revision History

Revision	Date	Changes / Comments
A	2003-08-07	Initial Release
B	2003-08-08	Added position number 28 to the shield can lid.
C	2003-09-24	Changed the product number for the front cover assembly from /2 to /8. Both parts are acceptable, but only /8 can be ordered at this time. Removed shield can lid. This part is only required at the HVC level.
D	2003-10-31	Removed "Do Not Use" statement from microphone grommet. Mandatory replacement is no longer required. Reuse or replace the grommet as necessary.