

Repair Movies - mechanical -



*Xperia XZ2 Compact
H8314, H8324 (Dual SIM)*

CONTENTS

| | | |
|-----|-------------------------|---|
| 1 | Disassembly Movie | 3 |
| 1.1 | Disassembly | 3 |
| 2 | Reassembly Movie | 4 |
| 2.1 | Reassembly | 4 |
| 3 | Revision History | 5 |

To view the embedded repair movies in this document, video play back application such as Media Player is required.

If the movies appear to be jerky or blurred when viewing on-line, this is probably caused by the connection speed being too slow.

In that case, right-click with the mouse on the document name and select Save Target As to download the repair movie document for off-line viewing.

1 Disassembly Movie

1.1 Disassembly

Double click the icon to play back the disassembly movie. →



Refer to Working Instruction 4. Disassembly for the details.

2 Reassembly Movie

2.1 Reassembly

Double click the icon to play back the reassembly movie. →



Procedures for Generic Wheel Press and Tool Press Tool for Bending Camera FPCs are omitted. Refer to Working Instruction 5. Reassembly for the details.

3 Revision History

| Rev. | Date | Changes / Comments |
|------|------------|--------------------|
| 1 | 2018-03-09 | Initial release |