
4. Array course control

4-1. Software Adjustments

Test Jig (GH80-03306A)



Serial Cable(CSA LL64151-A)



Power Supply Cable



RF CABLE(GH39-00599A)



TEST CABLE-0.4M(GH39-01020A)



TEST CABLE-1.5M(GH39-01022A)



4-2. Software Downloading


4-2-1. Pre-requisite for Downloading

- Downloader Program([OneNAND Downloder V1.5 Lite For PNX5230.exe](#))
- SGH-F250 Mobile Phone
- Data Cable
- Binary file, TFS file

4-2-2. S/W Downloader Program


■ Load the binary download program by executing the
[“OneNAND Downloder V1.5 Lite For PNX5230.exe”](#)

1. Select the connected serial port and the rate of speed
2. Select the check box, the mode you want to download.
 - if the binary file wanted, check only 'BIN'
 - if the tfs file wanted, check only 'TFS'
 - if all the files wanted, check 'BIN+TFS'



3. Select the file(s) what you want to download

- click 'BIN...' to select a binary file.
- click 'TFS...' to select a tfs file.



4. Click the 'DOWNLOAD' button to downloading